



# SportsTurf

IRRIGATION

"The Sprinkler Repair Specialists"

Servicing Golf Courses Nationwide

Featuring RAIN BIRD® and TORO® New and Rebuilt Products



(800) 492-8378 1019 "A" South Melrose Street, Placentia, CA 92870  
[www.sportsturfirrigation.com](http://www.sportsturfirrigation.com)

# TORO® FEATURING NEW AND REBUILT PRODUCTS

## 1" CONVERSIONS



**634 Drive** \$44.85

3-2540



**660 Conversion Assembly** \$48.30

89-8138



**734 Conversion Assembly** \$58.00

89-1982



**765 Conversion Assembly** \$73.00

89-7015

765 Repair \$44.00



**830 Conversion Assemblies**

834S 102-2530 \$62.00

835S 102-5391 \$77.00



**860 Conversion Assemblies**

864S 102-3212 \$82.00

865S 102-2550 \$82.00

## 1" COMPLETES



**634/660 HYD or COM** \$62.00 / \$66.00

**634/660 VIH** \$68.00 / \$74.00

**734 HYD or COM** \$75.00

**734 VIH** \$88.00

**765 HYD or COM** \$83.00

**765 VIH** \$102.00

**834/835 VIH SERIES** \$103.00 / \$134.00

**865 VIH** \$125.00

## 1 1/2" CONVERSIONS



**694 Drive** \$86.10

3-3585



**674 Conversion Assembly** \$66.10

9-3901



**754 Conversion Assembly** \$58.00

89-4359



**785 Conversion Assembly** \$77.00

89-6998

785 Repair \$44.00



**850 Conversion Assemblies**

854S 102-2532 \$64.00

855S 102-5393 \$78.00



**880 Conversion Assemblies**

884S 102-3214 \$84.00

885S 102-2552 \$89.00

## 1 1/2" COMPLETES



**655 HYD or COM** \$85.00

**655 VIH** \$93.00

**674 HYD or COM** \$97.00

**674 VIH** \$109.00

**754/785 HYD or COM** \$101.00 / \$112.00

**754/785 VIH** \$112.00 / \$128.00

**854/855 VIH SERIES** \$118.00 / \$138.00

**885 VIH** \$137.00



PART #	ITEM DESCRIPTION	PURCHASE NEW	PURCHASE REBUILT
<b>670 PARTS</b>			
9-3908	Drive Assembly	✓	✓
9-7407	Nozzle Base	✓	✓
360-0107	O-Ring Cap/Screws	✓	
360-0398	O-Ring Upper Nozzle Base	✓	
363-4103	O-Ring Housing, Outer	✓	
35-0530	Cap	✓	✓
9-5055	Spring Retainer	✓	✓
<b>730/750 PARTS</b>			
89-1293	Cap - 730	✓	✓
89-4812	Cap - 750	✓	✓
89-1589	Plug, Cap (Black)	✓	
102-0134	Retainer w/o O-Ring - 730	✓	✓
363-4167	O-Ring, Seal, Nozzle Base	✓	
363-4102	O-Ring Retainer - 730	✓	
363-4103	O-Ring Retainer - 750	✓	
102-4502	Drive Assembly	✓	✓
89-5979	Seal Kit, Retainer - 730	✓	✓
89-4352	Seal Kit, Retainer - 750	✓	✓
89-8907	Base Assembly, Nozzle	✓	✓
102-1874	Nozzle Less Cap - 730	✓	✓
89-878(X)	Nozzle, Main #31-37 (730) & #52-55 (750)	✓	✓
<b>760/780 PARTS</b>			
89-1952	Cap - 760	✓	✓
89-1584	Cap - 780	✓	✓
89-1220	Plug, Adjustment	✓	
363-3150	Set Screw	✓	
363-4039	Nut Jam	✓	
89-1589	Plug, Cap	✓	
89-1906	Nozzle Base Assembly	✓	✓
102-0057	Nozzle Base w/Back Nozzle	✓	
363-4102	O-Ring, Retainer - 760	✓	
363-4103	O-Ring, Retainer - 780	✓	
89-5979	Seal Kit, Retainer - 760	✓	✓
89-4352	Seal Kit, Retainer - 780	✓	
102-0134	Retainer w/o O-Ring - 760	✓	✓
89-19(X)(X)	Nozzle, Main #62-68 (760) & #82-89 (780)	✓	✓
102-4497	Drive Assembly - Part Circle	✓	✓
360-0107	O-Ring/Nozzle Base	✓	

**PART #****ITEM DESCRIPTION****PURCHASE  
NEW****PURCHASE  
REBUILT****(800) 492-8378****TOOLS**

995-15	Selector Tool - (Flag Key)	✓	
995-100	Valve Snap Ring Pliers	✓	
995-08	Valve Removal Tool - 1"	✓	
995-09	Valve Removal Tool 1-1/2"	✓	
995-76	Valve Insertion Tool - 1"	✓	
995-101	Valve Insertion Tool 1-1/2"	✓	
995-83	Multi-Purpose Tool	✓	
995-82	Arc Adjustment Tool T-Handle	✓	
995-55	Riser Hold-up Tool	✓	
995-85	Riser Removal Tool	✓	
995-102	Riser Hold-up Tool, Universal	✓	

**1" CASE PARTS**

35-9453	Case Only, COM w/o VIH	✓	✓
35-9421	Electric Case Only, N/S w/o VIH	✓	✓
89-4868	Electric Case Assy, N/S w/VIH & Pilot Valve Assembly	✓	✓
35-9418	Case Only, Hydraulic NO	✓	✓
89-1046	Valve Assembly, Hydraulic	✓	✓
89-1047	Valve Assembly, COM	✓	✓
89-1048	Valve Assembly, Electric	✓	✓
89-1048-99	Valve Assembly, Electric w/New Piston	✓	✓
89-1054	Piston Assembly, Electric	✓	
89-4702	Snap Ring, Valve Assembly	✓	✓
9-1876	Tubing, Poly 1/4" X 11.5"	✓	

**1 1/2" CASE PARTS**

3-3343	Case Only, Hydraulic, NO w/o VIH	✓	✓
3-3389	Case Only, Electric, w/o VIH	✓	✓
89-1016	Case Assembly, Electric w/VIH & Pilot Valve	✓	✓
3-3304	Snap Ring, Valve Assembly	✓	✓
102-4003	Valve Assembly, Electric, NC	✓	✓
102-4003-99	Valve Assembly, Electric, NC w/New Piston	✓	
89-1036	Valve Assembly, Hydraulic	✓	✓
102-5101	Piston Assembly, Electric	✓	✓
9-1876	Tubing, Poly 1/4" X 11.5"	✓	

**PILOT VALVES/SOLENOIDS**

89-0009	Pilot Valve Assembly, w/Round Solenoid 50-100 PSI		✓
89-1000	Pilot Valve Assembly, Less Round Solenoid	✓	✓
102-5178	Pilot Valve Assembly, Selectable Pressure w/Solenoid	✓	✓
102-5975	Pilot Valve Assembly, Selectable Pressure Less Solenoid	✓	✓
9-2701	Pilot Valve Assembly (Pre'86) w/Square Solenoid		✓
9-2701-99	Pilot Valve Assembly (Pre'86) Less Square Solenoid		✓
89-1905	Solenoid Assembly, N/S Round	✓	✓
D 2412	Solenoid - 3/4" 20 thread (Deere)		✓
3-2670	Solenoid Assembly, O/S Square	✓	



# TORO® CONTROLLER/COMPONENT REPAIR RATES

BRAND/MODEL	ITEM DESCRIPTION	REPAIR PRICE*
TORO/OSMAC	8-Station Triac Output Module	\$104.95
	Receiver/Decoder Module (Not Including Pager)	\$249.95
	RDR 16 to 48 Station Upgrade	\$209.95
TORO/NW8000	Timing Assembly	\$219.95
	Power Supply PCB	\$154.95
	Modem PCB	\$154.95
	Valve Voltage Monitor PCB	\$91.50
	Pump Current Monitor	\$60.50
	4-Station Triac PCB	\$40.00
TORO/NWLTC	Timing Assembly (All Versions)	\$219.95
	Modem PCB (All Versions)	\$154.95
	4-Station Relay Output Module	\$85.50
	8-Station Relay Output Module "Plus System"	\$155.95
TORO/VT3	Timing Assembly	\$249.95
TORO/VT4	Timing Assembly	\$249.95
TORO/VT II	Satellite Timing Assembly (Includes Parts)	\$275.00
	Satellite Receiver PCB	\$154.95
	Central Timing & Syringe Assembly (Includes Parts)	\$449.95

*\*Price includes all necessary labor and parts needed with the exception to: displays, membranes, keypads and physical damage. Extensive water, surge or multi-component parts failure is subject to additional parts and/or labor charges*

## RECONDITIONED FACE PLATES & SPARE PARTS

Call for availability of other spare clock parts and components



**Super TR-4  
Standard  
(BTSTR4-STD)**



**Super TR-8  
(BTSTR8-PLUS)**



**NW 8000 Face Plate  
(91-1952)**



**Line Receiver  
(9-7837)**



**VT-2 Face Plate  
(91-1685)**

**Inquire About 2-Way Radio Repair and Purchasing Spare Batteries**